


70/AE/1107EW/25-26
 Oct 15.08.2025

FITNESS CERTIFICATE		
1	Name of School	St. Johns School, Anchal
2	Name of Officer	Karthik S. , Assistant Engineer, LID and EW Section, Anchal
3	Location with Educational District/SubDistrict	Anchal, Punalur(Edu. Dist), Anchal (Sub Dist)
4	Classification of Buildings as specified in coloumn for the application for fitness certificate and size	
	(i) Permanent Single or multystoried	1X42.20mX8.40mX3.50m (RCC, 4 Storey, G+3)
		1X20.00mX8.40mX3.50m (RCC, 4 Storey, G+3)
		1X30.00mX8.40X3.50m (RCC, 3 Storey, G+2)
	(ii) Semi permanent	Nil
	(iii) Temporary shed	Nil
5	Period for which certificate is issued	2025 - 2026
6	Nature for which certificate is issued	Fitness certificate of School Building
7	Nature of Defects if any	
	a. Foundation& Basement	Nil
	b. Superstructure	Nil
	c. Doors and Windows	Nil
	d. Woodwork wrought and putup	Nil
	e. Roof	Nil
	f. Flooring	Nil
	g. Miscellaneous(Cracks)	Nil
8	Any major defects noticed which will render the building unsafe in any manner	Nil
9	Whether maintainance works have been done properly	Yes
10	Whether the structure is sound or not for conducting classes	Structures are sound under normal Wind and Weather conditions. Fire Safety norms as per NOC FRS/PLR/2764/2025/RENEWAL dated 26-04-2025 to be followed
Note 1. The stability of the structure should be examined also with reference to location, altitude,intensity of wind,exposure to flood etc. Note 2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate Certified that the School was inspected by me on 15/08/2025 and the buildings are found to be fit to conduct classes for the period 2025 - 2026 for the reasons stated above		
Place	Anchal	Signature
Date	15-08-25	Designation



Note- Safety accordance with fire and electric line to be ensured with concerned department

അസിസ്റ്റന്റ് എഞ്ചിനീയർ
 പി. എ. ഡി. & ഇ. ഡി. സെക്ഷൻ
 അഞ്ചൽ ഗ്രാമപഞ്ചായത്ത്